

49.47

35AA1

N E A

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM								Page 2 of 4		
Sewershed: Jones Falls				Company: Savin Engineers				Date: 7/15/08		
Test to be Performed:				Ground	Ground Condition:				Supervisor: GS	
Smoke: X Dyed Water:				Dry:X Damp: Wet:				·		
Manhole ID: S37AA1 007				Test ID: 0994-608				Notifications Made:X (Residents, Fire, 311)		
Field Sketch: (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)										
Defect		<u> </u>		Source	Ī		Drainage		Photo	
No.		Address		Туре	Location	Sector	Area	Severity	Number	
	408 Venable Av	ve.		03	09	02	100	04	OB01-01	
2	404 Venable Av	ve.		03	14	02	10	04	OB02-01	
3	3415 Brentwoo	d Ave.		16	14	02	100	04	OB03-01	
				OBSER\		CODES				
	Source Type	Location	Sector	Severity		Source Type	Location			
	Main Sewer	Paved Concrete	Public	No Smoke		MH Frame Seal	Non-Paved			
	Service Line	Paved Asphalt	Private	Trace		Storm Drain	Field/Woods			
	Cleanout	Paved Other		Moderate		Catch Basin/Inlet				
	Downspout	Driveway		Major		Storm Manhole	Golf Course			
	Area Drain	Sidewalk				Storm Ditch	Other			
	Driveway Drain	Curb				Excavation				
	Stairwell Drain	Yard- Front			16	Other				
	Foundation Drain	Yard-Back								
09	Building Interior	Yard- Side								

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page _3_ of _4	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/15/08
Test to be Performed:	Ground Condition:	Supervisor:
Smoke: _X Dyed Water:	Dry:X Damp: Wet:	GS
Manhole ID: S37AA1 007	Test ID: 0994-608	Notifications Made: x (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



0994-608_OB01-01



0994-608_OB02-01

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page _4_ of _4	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/15/08
Test to be Performed:	Ground Condition:	Supervisor:
Smoke: _X Dyed Water:	Dry:X Damp: Wet:	GS
Manhole ID: S37AA1 007	Test ID: 0994-608	Notifications Made: x (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



0994-608_OB03-01